

# Smoke and Dye Testing Summary

## High Level Sewershed

### Run Summary

| Test ID   | Test Type | Date Inspected | Company / Super. | Blower MH   | Ground Condition | Notification Made? | Total Length |
|-----------|-----------|----------------|------------------|-------------|------------------|--------------------|--------------|
| S1028-016 | Smoke     | 8/8/2008       | ADS/TM           | S07UU_001MH | Dry              | Yes                | 1,375.66     |



---

# Smoke and Dye Testing Summary

---

## High Level Sewershed

### Run Summary

| Test ID   | Test Type | Date Inspected | Company / Super. | Blower MH   | Ground Condition | Notification Made? | Total Length |
|-----------|-----------|----------------|------------------|-------------|------------------|--------------------|--------------|
| S1028-016 | Smoke     | 8/8/2008       | ADS/TM           | S07UU_001MH | Dry              | Yes                | 1,375.66     |

### Isolated Pipes

| Pipe ID     | Upstream MH | Downstream MH | Length (ft) | Diameter (In) |
|-------------|-------------|---------------|-------------|---------------|
| S07UU_001G1 | S07UU_001MH | S07UU_017MH   | 299.835     | 8             |
| S07UU_017G1 | S07UU_017MH | S07UU_016MH   | 300.3102    | 8             |
| S05WW_004G1 | S05WW_004MH | S07UU_001MH   | 267.8532    | 8             |
| S07UU_014G1 | S07UU_014MH | S07UU_007MH   | 167.0173    | 8             |
| S07UU_007G1 | S07UU_007MH | S07UU_002MH   | 171.9970    | 8             |
| S07UU_016G1 | S07UU_016MH | S07UU_014MH   | 168.6465    | 8             |

### Observations & Photos

**Obs\_ID** S1028-016-OB01

**Address** 3625 Springdale Ave

**Status** Private

**Source** Cleanout

**Location** Yard - back

**Nearest MH** S07UU\_017MH

**Comments** Smoke from cleanout in back yard. 3625 Springdale Ave.



**Picture** \S1028-016-OB01-P01.jpg

**Comments** Back of house, 3625 Springdale Ave.

**Obs\_ID** S1028-016-OB02

**Address** 3623 Springdale Ave

**Status** Private

**Source** Cleanout

**Location** Yard - back

**Nearest MH** S07UU\_017MH

**Comments** Smoke from cleanout in back yard. 3623 Springdale Ave.



**Picture** \S1028-016-OB02-P01.jpg

**Comments** Back of house, 3623 Springdale Ave.

---

# Smoke and Dye Testing Summary

---

## High Level Sewershed

### Run Summary

| Test ID   | Test Type | Date Inspected | Company / Super. | Blower MH   | Ground Condition | Notification Made? | Total Length |
|-----------|-----------|----------------|------------------|-------------|------------------|--------------------|--------------|
| S1028-016 | Smoke     | 8/8/2008       | ADS/TM           | S07UU_001MH | Dry              | Yes                | 1,375.66     |

**Obs\_ID** S1028-016-OB03

**Address** 3619 Springdale Ave

**Status** Private

**Source** Cleanout

**Location** Yard - back

**Nearest MH** S07UU\_016MH

**Comments** Smoke from cleanout in back yard. 3619 Springdale Ave.



**Picture** \S1028-016-OB03-P01.jpg

**Comments** Back of house, 3619 Springdale Ave.

**Obs\_ID** S1028-016-OB05

**Address** 3616 Fairview Ave

**Status** Private

**Source** Cleanout

**Location** Yard - back

**Nearest MH** S07UU\_016MH

**Comments** Smoke from cleanout in back yard. 3616 Fairview Ave.



**Picture** \S1028-016-OB05-P01.jpg

**Comments** Back of house, 3616 Fairview Ave.

**Obs\_ID** S1028-016-OB04

**Address** 3620 Fairview Ave

**Status** Private

**Source** Cleanout

**Location** Yard - back

**Nearest MH** S07UU\_017MH

**Comments** Smoke from cleanout in back yard. 3620 Fairview Ave.



**Picture** \S1028-016-OB04-P01.jpg

**Comments** Back of house, 3620 Fairview Ave.

**Obs\_ID** S1028-016-OB06

**Address** 3616 Fairview Ave

**Status** Private

**Source** Cleanout

**Location** Yard - back

**Nearest MH** S07UU\_016MH

**Comments** Smoke from cleanout in back yard. 3616 Fairview Ave.



**Picture** \S1028-016-OB06-P01.jpg

**Comments** Back of house, 3616 Fairview Ave.